Channel Yacht Sales Bristol thank you

VISA DEBIT *************9007 PAN SEQ NO: 00 AID: A0000000031010

ICC

SALE AMOUNT

£185.28

*** CUSTOMER COPY *** PLEASE RETAIN FOR YOUR RECORDS

PIN VERIFIED

AUTH: 014282 DATE: 25/05/13 TIME: 14:53

Boat Name:

Engine & Serial number

Job Description:

Removed seized tiller arm studs

Tohatsu M40C X2

22/03/12

Norkshop

Millie/ ruby

Replaced broke pinion and refitted tiller with new bushes and pinion Test Ran and adjusted motor in tank, Sealed carburettor idle and mixture screws

Yacht Sales Ltd

Diagnosed running fault , Replaced faulty earthing strap to coil Checked fuel pump operation

Test ran engine and adjusted in tank, sealed carburettor adjustments

Note:

Both motor have bee drained of fuel following running .

Item			Price eac	h	Line Total
	2 Nylor	2 Nylon Bushes)	£9.00
	2 Tiller	Bolts	£4.50)	£9.00
	1 Pinio	n	£7.20)	£7.20
	1 Sprin	• 1	£1.20)	£1.20
		acement earthing strap	£3.50)	£3.50
		1 Connection and Cable support 1 Lubrication and sundries		£2.00 £3.00	
	1 Lubrio				
Labour	0.5				
Laboui	3.5		£35.00		£122.50
				Parts	£31.90
				Labour	£122.50
				Subtotal	£154.40
				VAT	£30.88
				To Pay	£185.28





Customer Details

Tim walsh C/O UBUC **Bristol University** Bristol

