## BRISTOL CHANNEL DIVING REGULATOR SERVICE REPORT (F4)

Customer name BRISTOR UNI	Phone
Model Sculappo MKII	Phone.
WarrantyServiceHealth c	Serial No. 1074806662
Pre-disassembly I.P. 10.5 pei/bar	
External inspection	Condition
Disassemble	Pre strip test
Fit service kit.	Clean
325	Inspect remaining parts
Inform defective parts  Adjust I.P. 10.0 psi/bar	Reassemble
	Adjust 2 <sup>nd</sup> stage
Adjust octopus.	Final test
Inhalation effort!!	Leak test
Test pressure. Ze/Zoo	I.P. programs 4.11
Product codes 10.04245 / 11300045x2/Octo hase	
Product codes	
comments replace Octo hose 2nd st. 01	
procees to be supplied a futfed by customer	
such as a such a	
use, in addition to any seem of valves, most manufacturers suggest you perform	
It is our policy to seek training and advice from the equipment suppliers or manufacturers, however we does not affect your statutors sick.	
We will not real to replace. This	
mouthpieces. We do not inspect under hose protection, unless specifically asked, consoles are not All work is warranted for 2	
adjustment after 2 3 months if tamper paint seals are unbroken Some velocities	
and we will adjust this free of charge, usually, while you wait.  If your valve tastes strange, don't be alarmed, we only use non toxic cleaning agents and this taste will	
Next service due 27/10/16 Technician Foot	
Technician. 4100	Date 27/10/15