

BRISTOL CHANNEL DIVING REGULATOR SERVICE REPORT (F4)

Customer name Bristol Uni Phone.....

Model APEKS DS4 Serial No. 10064649

Warranty..... Service Health check..... Check fault.....

Pre-disassembly I.P. 10 psi / bar Condition Good

External inspection Pre strip test

Disassemble Clean

Fit service kit Inspect remaining parts

Inform defective parts Reassemble.....

Adjust I.P. 9 psi / bar Adjust 2nd stage

Adjust octopus Final test

Inhalation effort 1/4 " Leak test

Test pressure 20/200 I.P. pressure stable

Product code APO241 / APO219 / 11300045

Product code.....

Comments Replace Octo hose & low pressure hose.

IMPORTANT

We strongly recommend you test serviced equipment in a safe confined water such as a swimming pool prior to use in open water.

We have no fault to wet test valves, most manufacturers suggest you perform a vacuum test prior to use, in addition to any normal equipment checks.

It is our policy to seek training and advice from the equipment suppliers or manufacturers, however we reserve the right to use our judgement in the servicing of equipment as to which parts to replace. This does not affect your statutory rights.

We will not replace parts that are not standard service kit parts without your permission, such as mouthpieces, which are inspected under hose protection, unless specifically asked, consoles are not serviced unless specifically asked.

All work is warranted for 3 months if tamper paint seals are unbroken. Some valves may require slight adjustment after 24 hours, if you feel your valve has bedded in slightly loose or tight, please call in and we will adjust it free of charge, usually, while you wait.

If your valve has a strange taste, don't be alarmed, we only use non toxic cleaning agents and this taste will disappear after 24 hours.

Next service 27/10/16 Technician Brock Date 27/10/15