BRISTOL CHANNEL DIVING REGULATOR SERVICE REPORT (F4)

Customer name Bristoc UNI	Phone
Model Soubapro MAII	Serial No.06.0051.0445
Warranty Service Health check Check fault	
Pre-disassemi ly LP	Condition. Pool
External inspection	Pre strip test
Disassemble	Clean
Fit service to the se	Inspect remaining parts
Inform del "ve ; "ts	Reassemble
Adjust I.P	Adjust 2 nd stage
Adjust octo, 18	Final test
Inhalation ort. ///	Leak test
Test pressure. 20/200	I.P. pressure stable
Product cod 1004745 / 1/300045xZ /	
Product co. 13	122
Comments Replace 2nd stage 1	rose. Chen Octo e
2nd stage fruit covers. IMPORTANT	
We strow by recommend you test serviced equipment in a safe confined water such as a swimming pool prior to use in open water. We have no facility to wet test valves, most manufacturers suggest you perform a vacuum test prior to use, in addition to any normal equipment checks. It is our policy to seek training and advice from the equipment suppliers or manufacturers, however we reserve the right to use our judgement in the servicing of equipment as to which parts to replace. This does not affect your statutory rights. We will not reserve the set that are not standard service kit parts without your permission, such as mouthpieces. We do not inspect under hose protection, unless specifically asked, consoles are not serviced unless energically asked. All work is we enterficially asked. All work is we enterficially asked. All work is we enterficially asked for 3 months if tamper paint seals are unbroken. Some valves may require slight adjustment at 2-3 uses, if you feel your valve has bedded in slightly loose or tight, please call in and we will asset the free of charge, usually, while you wait. If your valve t istes stronge, don't be alarmed, we only use non toxic cleaning agents and this taste will disappear aficone.	
Next service due 21/w/16 Technician Brok Date 27/10/15	