

BRISTOL CHANNEL DIVING REGULATOR SERVICE REPORT (F4)

Customer name BRISTOL UNI Phone.....

Model SCUBAPRO MK II Serial No. 8060509554

Warranty..... Service Health check..... Check fault.....

Pre-disassemble I.P. 10.5 psi / bar Condition POOR

External inspection Pre strip test

Disassemble Clean

Fit service Inspect remaining parts

Inform defective parts Reassemble

Adjust I.P. 10 psi / bar Adjust 2nd stage

Adjust O₂ Final test

Inhalation 1/4 Leak test

Test pressure 20/200 I.P. pressure stable

Product # 10.042.45 / 11.300.045x2 /

Product # / /

Comments Replace O₂ hose, Replace valve housing on 2nd stage

IMPORTANT

We strongly recommend you test serviced equipment in a safe confined water such as a swimming pool prior to use in open water.

We have no facility to wet test valves, most manufacturers suggest you perform a vacuum test prior to use, in addition to any normal equipment checks.

It is our policy to seek training and advice from the equipment suppliers or manufacturers, however we reserve the right to use our judgement in the servicing of equipment as to which parts to replace. This does not affect your statutory rights.

We will not replace items that are not standard service kit parts without your permission, such as mouthpieces. We do not inspect under hose protection, unless specifically asked, consoles are not serviced unless specifically asked.

All work is warranted for 3 months if tamper paint seals are unbroken. Some valves may require slight adjustment after 2-3 uses, if you feel your valve has bedded in slightly loose or tight, please call in and we will adjust this free of charge, usually, while you wait.

If your valve tastes strange, don't be alarmed, we only use non toxic cleaning agents and this taste will disappear before the dive.

Next service due 27/10/16 Technician Brook Date 27/10/15