

+

BRISTOL CHANNEL DIVING REGULATOR SERVICE REPORT (F4)

Customer name BRISTOL UNIT Phone.....

Model APEKS DSA ATX 40/40 Serial No. 10064649

Warranty..... Service Health check..... Check fault.....

Pre-disassembly I.P. 8.4 psi / bar Condition FAIR

External inspection Pre strip test

Disassemble Clean

Fit service kit Inspect remaining parts

Inform defective parts N/A Reassemble

Adjust I.P. 9.5 psi / bar Adjust 2nd stage

Adjust octopus Final test

Inhalation effort 1/4 Leak test

Test pressure 30 - 190 BAR I.P. pressure stable

Product codes...../...../.....

Product codes...../...../.....

Comments.....

IMPORTANT

We strongly recommend you test serviced equipment in a safe confined water such as a swimming pool prior to use in open water.

We have no facility to wet test valves, most manufacturers suggest you perform a vacuum test prior to use, in addition to any normal equipment checks.

It is our policy to seek training and advice from the equipment suppliers or manufacturers; however we reserve the right to use our judgement in the servicing of equipment as to which parts to replace. This does not affect your statutory rights.

We will not replace items that are not standard service kit parts without your permission, such as mouthpieces. We do not inspect under hose protection, unless specifically asked, consoles are not serviced unless specifically asked.

All work is warranted for 3 months, if tamper paint seals are unbroken. Some valves may require slight adjustment after 2 - 3 uses, if you feel your valve has bedded in slightly loose or tight, please call in and we will adjust this free of charge, usually, while you wait.

If your valve tastes strange, don't be alarmed, we only use non toxic cleaning agents and this taste will disappear after one dive.

Next service due 19/10/17 Technician G. Stillings Date 18/10/16