



Service Reference No	DM20284
----------------------	---------

**DM SCUBA TRAINING
REGULATOR SERVICE REPORT**

Ry 040

Owners Name	Bristol Uni SAC	Contact Number	07557 882538
Work Required		Service as required	
Make	Apeks	Model	DS4/2 x ATX40
		Serial	1603 03076
Condition	Good	Pre-Service Intermediate Pressure @200Bar	
		9.5	Bar
External Inspection		Satisfactory	Pre-strip test
		Satisfactory	
Disassemble	Satisfactory	Clean and inspect parts	
		Satisfactory	
Reassemble	Satisfactory	Gauge	None

Post service intermediate pressure @ 20Bar tank pressure	9.5	Bar
Post service intermediate pressure @ 200Bar tank pressure	9.7	Bar
Adjust primary Second Stage	Satisfactory	Inhalation effort
		1.5
		"H2O
Adjust Secondary Second Stage	Satisfactory	Inhalation effort
		1.4
		"H2O
Leak test	Satisfactory	Final test
		Satisfactory

Part Used	2 x Apeks 2nd stage kits	1 x Apeks 1st stage kit
	02 Grease	

Comments

IMPORTANT PLEASE READ

We strongly recommend you test serviced equipment in a safe confined water such as a swimming pool prior to use in Open Water

We have no facility to wet test regulators, most manufacturers suggest you perform a vacuum test prior to use, in addition to any normal equipment checks. We will not replace items that are not in a standard service kit without your prior permission. All work is warranted for 3 months, if tamper proof paint seals are unbroken. Some valves may require a slight adjustment after 2-3 weeks of use. If you feel that your valve has bedded in slightly loose or tight, please return the valve and we will adjust it free of charge, usually while you wait.

Service Date	24-Oct-17	Technician	<i>P M Dowding</i> (P M Dowding)
		Service Kits	£45.00
		Labour	£25.00
		Amount Payable	£70.00
Next Service	25-Oct-18		

Tel: 07920 556116
email: instructor@hotmail.co.uk
web: www.dm-scuba.co.uk